


# VMAX Series Parts List



1. Left end cap	13. Stand of motor
2. Screw of housing	14. Motor
3. Circuit board	15. Right end cap
4. Insulating strip	16. Screen material
5. Copper pillar of check bracket	17. Bottom bar
6. Check bracket	18. Sleeve of bottom bar
7. Stopper	
8. Aluminum shaft	
9. Power cord	
10. Housing	
11. Drive head	
12. Bearing	